# Hybrid 3z39 Traveler

October 4, 1999

## 1 Connectivity

Repairs on shorts:

Fixes for opens:

## 2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 3Z39 has die: 075-022 075-023 075-029

## 3 Bad Channels

The following channels were bad or exceedingly noisy:

## 4 Comments

No comments.

# 5 Pedestal

The following plot shows the pedestals vs. channel number with and without charge injection:

**Pedestal for each Channel**




The following plot shows the average pedestal vs. pipeline cell ID with and without charge injection. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 on chip 1 is at x=5, chip 2 at x=49, chip 3 at x=97, etc.

**Pedestal vs. Pipeline Cell ID**



# 6 Noise

The following plots show the single-cell and multi-cell RMS noise:

**RMS Noise**




The upper plot shows the difference between the pedestal of each channel and the average pedestal and the lower plots shows the RMS noise of all the channels:

**Distribution of pedestals and noise**



# 7 Dynamic Threshold Subtraction

The following plot shows the readout of channels with charge injection with the dynamic threshold subtraction turned on:

**Dynamic Threshold Subtraction**