Hybrid 2p29 Traveler

September 28, 1999

1 Connectivity

2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 2P29 has die: 136-017 136-029

3 Bad Channels

The following channels were bad or exceedingly noisy: Cells 82 and 83 are noisy.

4 Comments

5 Pedestal

The following plot shows the pedestals vs. channel number

Pedestal



The following plot shows the average pedestal vs. pipeline cell ID. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 on chip 1 ia at x=5, chip 2 at x=49, chip 3 at x=97, etc.

Pedestal vs. Pipeline Cell ID



6 Noise

The following plot shows the single cell RMS noise:

RMS Noise



The following plot show the multi-cell RMS noise:

Multi-Cell Noise



7 Dynamic Threshold Subtraction

The following plot shows the readout of channels with charge injection with the dynamic threshold subtraction turned on:

Dynamic Threshold Subtraction