Hybrid 2p51 Traveler

December 2, 1999

1 Connectivity

Repairs on shorts:

Fixes for opens: TN open in hybrid, fixed with red wire and w/b. DVDD open at connector field. Fixed with red wire. BECLK open between solder field and term. resistor. fixed with red wire. too many kludges. "data source".

2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 2P51 has die: 046-016 046-018

3 Data Analysis Summary

The following summarizes the findings of the Burn-in data analysis program. The first chip in the readout name is numbered 0.

```
% Hybrid 2p51 classification info. Created 10:16:18 11/22/99

Hybrid 2p51 quality: fair
Chip classification: good fair
Bad channels (chip-channel): 1-90
Bad cells: none
Random bad capacitors (chip-cell-channel): 1-39-90
Channels at pedestal needed for DCMS: 32.7 34.7
```

4 Comments

Has automatic chip-to-chip wirebonds.

5 Pedestal

The following plot shows the pedestals vs. channel number with and without charge injection:

Pedestal for each Channel



The following plot shows the average pedestal vs. pipeline cell ID with and without charge injection. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 for chip 1 is at x=5, chip 2 at x=51, chip 3 at x=97, etc.

Pedestal vs. Pipeline Cell ID



6 Noise

The following plots show the single-cell and multi-cell RMS noise:

RMS Noise





The following are histograms of the pedestal of each pipeline capacitor relative to the chip average (top); and the RMS noise of each capacitor (bottom):

Distribution of Pedestals and Noise





7 Currents

The following plots show the supply currents per chip as a function of measurment number. Currents are measured approximately every 10 minutes:

Supply Currents During Burn-in