Hybrid 2z119 Traveler

November 3, 1999

1 Connectivity

Repairs on shorts:

Fixes for opens:

2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 2Z119 has die: 078-031 078-013

3 Comments

This is a JUNK hybrid meant for wirebonding practice at FNAL.