Hybrid 3z124 Traveler

December 14, 1999

1 Connectivity

Repairs on shorts:

Fixes for opens: HV open. Fixed w/ wire from 10k resistor to neiboring pad.

2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 3Z124 has die: 199-061 199-062 199-063

3 Data Analysis Summary

The following summarizes the findings of the Burn-in data analysis program. The first chip in the readout name is numbered 0.

```
% Hybrid 3z124 classification info. Created 13:39:31 12/13/99

Hybrid 3z124 quality: fair
Chip classification: good good fair
Bad channels: none
Bad cells: none
Random bad capacitors (chip-cell-channel): 2-41-65 2-42-99
Channels at pedestal needed for DCMS: 27.3 30.7 28.5
```

4 Comments

Has Au finger DVDD and DGND wirebonds.
HV Test.

5 Pedestal

The following plot shows the pedestals vs. channel number with and without charge injection:

Pedestal for each Channel



The following plot shows the average pedestal vs. pipeline cell ID with and without charge injection. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 for chip 1 is at x=5, chip 2 at x=51, chip 3 at x=97, etc.

Pedestal vs. Pipeline Cell ID



6 Noise

The following plots show the single-cell and multi-cell RMS noise:

RMS Noise





The following are histograms of the pedestal of each pipeline capacitor relative to the chip average (top); and the RMS noise of each capacitor (bottom):

Distribution of Pedestals and Noise





7 Currents

The following plots show the supply currents per chip as a function of measurment number. Currents are measured approximately every 10 minutes:

Supply Currents During Burn-in