Hybrid 3z94 Traveler

December 14, 1999

1 Connectivity

Repairs on shorts:

Fixes for opens: HV open. Fixed w/ wire from 10k resistor to neighboring pad.

2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 3Z94 has die: 199-027 199-028 199-029

3 Data Analysis Summary

The following summarizes the findings of the Burn-in data analysis program. The first chip in the readout name is numbered 0.

```
% Hybrid 3z94 classification info. Created 13:53:38 12/13/99

Hybrid 3z94 quality: fair
Chip classification: fair good good
Bad channels (chip-channel): 0-79
Bad cells: none
Random bad capacitors: none
Channels at pedestal needed for DCMS: 28.7 29.7 29.7
```

4 Comments

Has Au finger bonds for FE DVDD and DGND.
HV Test.

5 Pedestal

The following plot shows the pedestals vs. channel number with and without charge injection:



The following plot shows the average pedestal vs. pipeline cell ID with and without charge injection. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 for chip 1 is at x=5, chip 2 at x=51, chip 3 at x=97, etc.



6 Noise

The following plots show the single-cell and multi-cell RMS noise:

RMS Noise





The following are histograms of the pedestal of each pipeline capacitor relative to the chip average (top); and the RMS noise of each capacitor (bottom):

Distribution of Pedestals and Noise





7 Currents

The following plots show the supply currents per chip as a function of measurment number. Currents are measured approximately every 10 minutes:

Supply Currents During Burn-in