Hybrid 5p0 Traveler

December 14, 1999

1 Connectivity

Repairs on shorts:

Fixes for opens:

2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 5P0 has die: 094-007 094-008 094-010 094-011 094-013

3 Data Analysis Summary

The following summarizes the findings of the Burn-in data analysis program. The first chip in the readout name is numbered 0.

```
% Hybrid 5p0 classification info. Created 15:05:01 12/13/99

Hybrid 5p0 quality: fair
Chip classification: fair good good good good
Bad channels (chip-channel): 0-100
Bad cells: none
Random bad capacitors: none
Channels at pedestal needed for DCMS: 37.7 35.6 33.7 39.6 37.6
```

4 Comments

Has encapsulation.
Has Au finger DVDD and DGND wirebonds.
HV Test.

5 Pedestal

The following plot shows the pedestals vs. channel number with and without charge injection:



The following plot shows the average pedestal vs. pipeline cell ID with and without charge injection. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 for chip 1 is at x=5, chip 2 at x=51, chip 3 at x=97, etc.



6 Noise

The following plots show the single-cell and multi-cell RMS noise:

RMS Noise





The following are histograms of the pedestal of each pipeline capacitor relative to the chip average (top); and the RMS noise of each capacitor (bottom):

Distribution of Pedestals and Noise





7 Currents

The following plots show the supply currents per chip as a function of measurment number. Currents are measured approximately every 10 minutes:

Supply Currents During Burn-in