# Hybrid 5z117 Traveler

February 8, 2000

## 1 Connectivity

Repairs on shorts:

Fixes for opens:

## 2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 5Z117 has die: 095-022 095-024 095-025 095-028 095-029

## 3 Data Analysis Summary

The following summarizes the findings of the Burn-in data analysis program. The first chip in the readout name is numbered 0.

```
% Hybrid 5z117 classification info. Created 10:58:46 02/02/00

Hybrid 5z117 quality: fair
Chip classification: fair good good good good
Bad channels (chip-channel): 0-59
Bad cells: none
Random bad capacitors: none
Channels at pedestal needed for DCMS: 32.8 33.7 31.3 33.7 34.6
```

## 4 Comments

Encapsulated. FE DV finger gold bonds. HV tested.

# 5 Pedestal

The following plot shows the pedestals vs. channel number with and without charge injection:

**Pedestal for each Channel**




The following plot shows the average pedestal vs. pipeline cell ID with and without charge injection. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 for chip 1 is at x=5, chip 2 at x=51, chip 3 at x=97, etc.

**Pedestal vs. Pipeline Cell ID**



# 6 Noise

The following plots show the single-cell and multi-cell RMS noise:

**RMS Noise**







The following are histograms of the pedestal of each pipeline capacitor relative to the chip average (top); and the RMS noise of each capacitor (bottom):

**Distribution of Pedestals and Noise**






# 7 Currents

The following plots show the supply currents per chip as a function of measurment number. Currents are measured approximately every 10 minutes:

**Supply Currents During Burn-in**