Hybrid 6p96 Traveler

January 7, 2000

1 Connectivity

Repairs on shorts:

Fixes for opens:

2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 6P96 has die: 215-088 215-090 215-094 215-095 215-096 215-097

3 Data Analysis Summary

The following summarizes the findings of the Burn-in data analysis program. The first chip in the readout name is numbered 0.

```
% Hybrid 6p96 classification info. Created 14:08:20 01/07/00

Hybrid 6p96 quality: fair
Chip classification: fair good fair good fair fair
Bad channels (chip-channel): 0-104 2-32
Bad cells: none
Random bad capacitors (chip-cell-channel): 4-26-63 5-26-41
Channels at pedestal needed for DCMS: 33.7 32.6 33.6 34.6 31.6 32.7
```

4 Comments

Has Au FE DDVD and DGND bonds
HV test

5 Pedestal

The following plot shows the pedestals vs. channel number with and without charge injection:



The following plot shows the average pedestal vs. pipeline cell ID with and without charge injection. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 for chip 1 is at x=5, chip 2 at x=51, chip 3 at x=97, etc.



6 Noise

The following plots show the single-cell and multi-cell RMS noise:

RMS Noise





The following are histograms of the pedestal of each pipeline capacitor relative to the chip average (top); and the RMS noise of each capacitor (bottom):

Distribution of Pedestals and Noise





7 Currents

The following plots show the supply currents per chip as a function of measurment number. Currents are measured approximately every 10 minutes:

Supply Currents During Burn-in