Hybrid 7p179 Traveler

February 9, 2000

1 Connectivity

Repairs on shorts:

Fixes for opens: BN open on hybrid; fixed with wire.

2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 7P179 has die: 141-053 141-054 141-055 141-056 141-058 141-059 141-060

3 Data Analysis Summary

The following summarizes the findings of the Burn-in data analysis program. The first chip in the readout name is numbered 0.

```
% Hybrid 7p179 classification info. Created 12:12:12 02/09/00

Hybrid 7p179 quality: fair
Chip classification: good good good good good fair good
Bad channels (chip-channel): 5-50
Bad cells: none
Random bad capacitors (chip-cell-channel): 5-35-50 5-40-50 5-41-50
   5-42-50 5-43-50 5-44-50
Channels at pedestal needed for DCMS: 31.7 31.7 31.6 33.6 31.5 31.7 29.6
```

4 Comments

Encapsulated. FE DV finger gold bonds. HV tested.

5 Pedestal

The following plot shows the pedestals vs. channel number with and without charge injection:

Pedestal for each Channel



The following plot shows the average pedestal vs. pipeline cell ID with and without charge injection. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 for chip 1 is at x=5, chip 2 at x=51, chip 3 at x=97, etc.

Pedestal vs. Pipeline Cell ID



6 Noise

The following plots show the single-cell and multi-cell RMS noise:

RMS Noise





The following are histograms of the pedestal of each pipeline capacitor relative to the chip average (top); and the RMS noise of each capacitor (bottom):

Distribution of Pedestals and Noise





7 Currents

The following plots show the supply currents per chip as a function of measurment number. Currents are measured approximately every 10 minutes:

Supply Currents During Burn-in