Hybrid 8j111 Traveler

January 4, 2000

1 Connectivity

Repairs on shorts:

Fixes for opens:

2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 8J111 has die: 028-046 191-051 191-054 029-007 198-004 198-008 198-009 198-012

3 Data Analysis Summary

The following summarizes the findings of the Burn-in data analysis program. The first chip in the readout name is numbered 0.

```
% Hybrid 8j111 classification info. Created 11:44:53 12/06/99

Hybrid 8j111 quality: bad
Chip classification: fair good good bad good fair fair good
Bad channels (chip-channel): 3-39 3-51 3-52 5-29 6-7 6-35
Bad cells: none
Random bad capacitors (chip-cell-channel): 0-25-47 3-32-40 5-8-26
   5-8-27
Channels at pedestal needed for DCMS: 33.6 30.6 31.7 31.6 28.6 29.6 29.4 30.7
```

4 Comments

No comments.

5 Pedestal

The following plot shows the pedestals vs. channel number with and without charge injection:

Pedestal for each Channel



The following plot shows the average pedestal vs. pipeline cell ID with and without charge injection. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 for chip 1 is at x=5, chip 2 at x=51, chip 3 at x=97, etc.

Pedestal vs. Pipeline Cell ID



6 Noise

The following plots show the single-cell and multi-cell RMS noise:

RMS Noise





The following are histograms of the pedestal of each pipeline capacitor relative to the chip average (top); and the RMS noise of each capacitor (bottom):

Distribution of Pedestals and Noise





7 Currents

The following plots show the supply currents per chip as a function of measurment number. Currents are measured approximately every 10 minutes:

Supply Currents During Burn-in