Hybrid 8j131 Traveler

December 16, 1999

1 Connectivity

Repairs on shorts:

Fixes for opens:

2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 8J131 has die: 196-038 196-040 196-041 196-047 197-004 197-006 197-007 197-010

3 Data Analysis Summary

The following summarizes the findings of the Burn-in data analysis program. The first chip in the readout name is numbered 0.

```
% Hybrid 8j131 classification info. Created 17:21:17 12/10/99

Hybrid 8j131 quality: fair
Chip classification: fair good fair good good fair good fair
Bad channels (chip-channel): 0-1 2-76 2-105 5-97 5-102 7-121
Bad cells: none
Random bad capacitors (chip-cell-channel): 0-32-1 5-21-74 5-22-9
   5-4-122
Channels at pedestal needed for DCMS: 30.7 30.6 29.6 31.6 29.6 30.7 31.5 30.0
```

4 Comments

No comments.

5 Pedestal

The following plot shows the pedestals vs. channel number with and without charge injection:

Pedestal for each Channel



The following plot shows the average pedestal vs. pipeline cell ID with and without charge injection. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 for chip 1 is at x=5, chip 2 at x=51, chip 3 at x=97, etc.

Pedestal vs. Pipeline Cell ID



6 Noise

The following plots show the single-cell and multi-cell RMS noise:

RMS Noise





The following are histograms of the pedestal of each pipeline capacitor relative to the chip average (top); and the RMS noise of each capacitor (bottom):

Distribution of Pedestals and Noise





7 Currents

The following plots show the supply currents per chip as a function of measurment number. Currents are measured approximately every 10 minutes:

Supply Currents During Burn-in