Hybrid 8j315 Traveler

June 13, 2000

1 Connectivity

Repairs on shorts:
Fixes for opens:

2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 8J315 has die: 154-020 156-091 156-092 156-093 247-062 247-063 247-064 247-065

3 Data Analysis Summary

The following summarizes the findings of the Burn-in data analysis program. The first chip in the readout name is numbered 0.

```
% Hybrid 8j315 classification info. Created 11:08:10 06/12/00

Hybrid 8j315 quality: fair
Chip classification: good fair good fair good good good good
Bad channels (chip-channel): 3-109
Bad cells: none
Random bad capacitors (chip-cell-channel): 1-24-97 1-39-59
Channels at pedestal needed for DCMS: 31.7 32.7 34.5 31.6 33.7 33.7 31.6 33.7
```

4 Comments

HV tested.

5 Pedestal

The following plot shows the pedestals vs. channel number with and without charge injection:



The following plot shows the average pedestal vs. pipeline cell ID with and without charge injection. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 for chip 1 is at x=5, chip 2 at x=51, chip 3 at x=97, etc.



6 Noise

The following plots show the single-cell and multi-cell RMS noise:

RMS Noise





The following are histograms of the pedestal of each pipeline capacitor relative to the chip average (top); and the RMS noise of each capacitor (bottom):

Distribution of Pedestals and Noise





7 Currents

The following plots show the supply currents per chip as a function of measurment number. Currents are measured approximately every 10 minutes:

Supply Currents During Burn-in