Hybrid 8j37 Traveler

December 16, 1999

1 Connectivity

Repairs on shorts:

Fixes for opens:

2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 8J37 has die: 048-024 048-026 048-027 048-029 045-041 045-042 045-043 045-045

3 Data Analysis Summary

The following summarizes the findings of the Burn-in data analysis program. The first chip in the readout name is numbered 0.

```
% Hybrid 8j37 classification info. Created 15:41:23 11/22/99

Hybrid 8j37 quality: bad
Chip classification: bad bad bad bad bad bad bad bad
Bad channels: N_bad_total = 1024 (too many to list all of them)
Bad cells: N_bad_total = 230 (too many to list all of them)
Random bad capacitors: none
Channels at pedestal needed for DCMS: 34.6 34.6 32.7 35.7 32.7 36.7 33.5 33.7
```

4 Comments

No comments.

5 Pedestal

The following plot shows the pedestals vs. channel number with and without charge injection:

Pedestal for each Channel



The following plot shows the average pedestal vs. pipeline cell ID with and without charge injection. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 for chip 1 is at x=5, chip 2 at x=51, chip 3 at x=97, etc.

Pedestal vs. Pipeline Cell ID



6 Noise

The following plots show the single-cell and multi-cell RMS noise:

RMS Noise





The following are histograms of the pedestal of each pipeline capacitor relative to the chip average (top); and the RMS noise of each capacitor (bottom):

Distribution of Pedestals and Noise





7 Currents

The following plots show the supply currents per chip as a function of measurment number. Currents are measured approximately every 10 minutes:

Supply Currents During Burn-in