Hybrid 8j378 Traveler

August 4, 2000

1 Connectivity

Repairs on shorts:
Fixes for opens:

2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 8J378 has die: 232-052 232-060 232-061 232-067 221-022 240-088 240-089 240-094

3 Data Analysis Summary

The following summarizes the findings of the Burn-in data analysis program. The first chip in the readout name is numbered 0.

```
% Hybrid 8j378 classification info. Created 11:56:04 07/28/00

Hybrid 8j378 quality: bad
Chip classification: good fair bad fair good good fair good
Bad channels (chip-channel): 1-8 2-24 2-40 2-99 3-10 3-109 6-23
Bad cells: none
Random bad capacitors: none
Channels at pedestal needed for DCMS: 31.7 31.5 30.7 30.7 30.8 31.7 32.6 32.5
```

4 Comments

HV tested.

5 Pedestal

The following plot shows the pedestals vs. channel number with and without charge injection:

Pedestal for each Channel



The following plot shows the average pedestal vs. pipeline cell ID with and without charge injection. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 for chip 1 is at x=5, chip 2 at x=51, chip 3 at x=97, etc.

Pedestal vs. Pipeline Cell ID



6 Noise

The following plots show the single-cell and multi-cell RMS noise:

RMS Noise





The following are histograms of the pedestal of each pipeline capacitor relative to the chip average (top); and the RMS noise of each capacitor (bottom):

Distribution of Pedestals and Noise





7 Currents

The following plots show the supply currents per chip as a function of measurment number. Currents are measured approximately every 10 minutes:

Supply Currents During Burn-in