Hybrid 8j379 Traveler

July 17, 2000

1 Connectivity

Repairs on shorts:
Fixes for opens:

2 Chips

The following chips were assembled on this hybrid (in the order that the chips get read out):
Hybrid 8J379 has die: 242-102 232-077 232-084 232-093 240-096 240-098 240-101 240-104

3 Data Analysis Summary

The following summarizes the findings of the Burn-in data analysis program. The first chip in the readout name is numbered 0.

```
% Hybrid 8j379 classification info. Created 13:03:29 07/03/00

Hybrid 8j379 quality: fair
Chip classification: good fair fair fair good fair good good
Bad channels (chip-channel): 1-32 1-33 2-82 2-102 3-79 3-80 5-113
Bad cells: none
Random bad capacitors: none
Channels at pedestal needed for DCMS: 32.6 30.7 31.7 30.7 30.7 30.8 31.6 32.5
```

4 Comments

HV tested.

5 Pedestal

The following plot shows the pedestals vs. channel number with and without charge injection:

Pedestal for each Channel



The following plot shows the average pedestal vs. pipeline cell ID with and without charge injection. The x-axis is cell ID offset by 46 for each chip. Thus cell ID 5 for chip 1 is at x=5, chip 2 at x=51, chip 3 at x=97, etc.

Pedestal vs. Pipeline Cell ID



6 Noise

The following plots show the single-cell and multi-cell RMS noise:

RMS Noise





The following are histograms of the pedestal of each pipeline capacitor relative to the chip average (top); and the RMS noise of each capacitor (bottom):

Distribution of Pedestals and Noise





7 Currents

The following plots show the supply currents per chip as a function of measurment number. Currents are measured approximately every 10 minutes:

Supply Currents During Burn-in