Silicon Tracks See Beam Spot

- During $36x36$ collisions in April, 2001, we had 2 wedges of silicon detector integrated as test of full system
- Able to measure position of interaction point
- Measurement confirmed by independent devices (COT, calorimeter)



Cluster Charge

- Silicon sensors in good working order. Cluster charges are Landau distributions.